

# Environmental Impact Assessment Report

**Proposed Mixed Use Residential Led Development Comprising 198 No.  
'Build-To-Rent' Apartment Units, Residents' Amenity Spaces And Facilities,  
Café/Restaurant, Replacement Office Use and Ancillary Accommodation and  
Works**

**At 42A Parkgate Street, Dublin 8.**

**For Ruirside Developments Ltd.**

**Prepared By: -**



26 / 27 Upper Pembroke Street, Dublin 2, D02 X361  
Phone: + 353 (1) 676 6507 § Email: info@sla-pdc.com

**In Association with: -**

Reddy Architecture & Urbanism in association with Glenn Howells Architects, Arup Consulting Engineers,  
Moore Group, AWN Consulting, ARC Heritage Consultants, Courtney Deery Archaeological  
Consultants

**JUNE 2021**

## **TABLE OF CONTENTS OF THE ENVIRONMENTAL IMPACT ASSESSMENT REPORT**

### **EIAR VOLUME 1- NON-TECHNICAL SUMMARY AND GLOSSARY**

### **EIAR VOLUME 2 – WRITTEN STATEMENT**

- Chapter 1 – Introduction
- Chapter 2 – Examination of Alternatives
- Chapter 3 – Description of Proposed Development
- Chapter 4 – Construction Strategy
- Chapter 5 – Planning and Policy
- Chapter 6 – Transport
- Chapter 7 – Air Quality
- Chapter 8 – Climate
- Chapter 9 – Noise and Vibration
- Chapter 10 – Biodiversity – Flora and Fauna
- Chapter 11 – Archaeology & Cultural Heritage
- Chapter 12 – Architectural Heritage Impact Assessment
- Chapter 13 – Landscape and Visual Impact Assessment
- Chapter 14 – Water
- Chapter 15 – Land and Soils
- Chapter 16 – Hydrogeology
- Chapter 17 – Material Assets - Waste Management
- Chapter 18 – Population and Human Health
- Chapter 19 – Material Assets – Utilities and Telecommunications
- Chapter 20 – Major Accidents and Disasters
- Chapter 21 – Cumulative Impacts and Interactions
- Chapter 22 – Summary of Mitigation, Monitoring and Residual Effects
- Chapter 23 – Bibliography

### **EIAR VOLUME 3 – APPENDICIES**

- Appendix 4.1- Construction and Environmental Management Plan (CEMP)- Block A
- Appendix 8.1- Microclimatic Wind Analysis and Pedestrian Comfort
- Appendix 8.2- Daylight and Sunlight Analysis
- Appendix 10.1- Report for the Purposes of Appropriate Assessment Screening
- Appendix 10.2- Natura Impact Statement
- Appendix 10.3- Pre-Demolition Bat Survey Report

- Appendix 11.1- Relevant Legislation
- Appendix 11.2- Glossary of Impact Assessment and Assessment Methodology
- Appendix 11.3- Archaeological Assessment Monitoring of Ground Investigation Works
- Appendix 11.4- Archaeological Assessment Report
- Appendix 13.1- Parkgate Street Verified Photomontages
- Appendix 13.2- Ariel Views Context Sections Anonometric Views Computer Generated Images
- Appendix 14.1- Site Specific Flood Risk Assessment
- Appendix 15.1- Figures
- Appendix 15.2- Ground Investigation IGSL Report No. 8483 Hickey & Co., Parkgate Street on behalf of ARUP Consulting Engineers
- Appendix 15.3- Geotechnical and Environmental Assessment
- Appendix 15.4- Ground Investigations Ireland Hickeys 43 Parkgate Place Ground Investigation Report
- Appendix 15.5- Preliminary Site Assessment
- Appendix 15.6- Detailed Site Assessment
- Appendix 16.1- Figures
- Appendix 17.1- Constuction and Demolition Waste Management Plan
- Appendix 17.2- Operational Waste Management Plan
- Appendix 18.1- Childcare Needs Assessment
- Appendix 18.2- Community and Social Infrastructure Audit
- Appendix 19.1- Utilities and Services Plans
- Appendix 19.2- Specific Assessment- Section 3.2 of the Building Height Guidelines (2018) (Telecommunications Report)
- Appendix 21.1- Cumulative Development